APPENDIX F Estimated Dredge Volumes at Piers

Richmond-San Rafael Bridge Seismic Retrofit Pier Excavation and Backfill Quantities

Pier #	Volume of Sediment Removed (Cubic Yards)			Volume of Backfill (Cubic Yards)
	Pier Excavation		Total	Backfill
	CONCRET	E TRESTLE SEC	TION	P.A. Joseph Co.
Concrete Trestle	0	7,200	7,200	0
8	BARGE A	CCESS DREDGI		
Barge Access Dredging			135,000	0
- h		ROACH STRUCT	URE	
A ^b 1 ^b	154	17	171	140
	154	23	177	140
2 ^b	224	26	250	140
3 ^b	98	28	126	140
4 ^b	98	30	128	140
5 ^b	98	35	133	140
6 ^b	84	23	107	140
	117	23	140	140
8 ^b	275	23	298	175
9 _p	178	26	204	175
10 ^b	381	26	407	175
11b	273	26	299	175
12 ^b	270	28	298	175
13 ^b	511	28	539	175
14 ^b	178	28	206	
15 ^b	178	28		175
16 ^b	270	27	206	175
17 ^b	178		297	175
18 ^b	270	28	206	175
19°		28	298	175
Total	1,218	2,242	3,460	372
verage per Pier	5,207 274	2,743	7,950	3,417
30 Post 10:		144 STRUCTURE	418	180
20	405	566	972	100
21	959	723	1,682	186 186
22	405	723	1,128	186
23	405	723	1,128	186
24	417	723	1,140	192
25	589	723	1,312	192
26	262	723	985	192
27	628	832	1,460	204
28	628	832	1,460	204
29	830	832	1,662	204
30°	1,029	1,570	2,599	372
31	445	832	1,277	204
32 33	628	832	1,460	204
33 34°	1,295	832	2,127	204
	5,371	2,193	7,564	598
35°	2,185	2,193	4,378	598
36	1,052	983	2,035	204
37 38	613	1,059	1,672	199
39 ^b	810	832	1,642	199
	296	24	320	209
40 ^b	195	38	233	209
41	273	1,097	1,370	199

Richmond-San Rafael Bridge Seismic Retrofit Pier Excavation and Backfill Quantities

Pier #	Volum	Volume of Sediment Removed (Cubic Yards)		
	Pier Excavation	Pile Clean-out	Total	(Cubic Yards) Backfill
42	1,027	1,172	2,199	199
43	615	868	1,483	199
44 ^c	796	1,102	1,898	352
45	434	868	1,302	199
46	830	1,059	1,889	204
47 ^c	2,859	2,036	4,895	539
48 ^c	3,417	1,868	5,285	539
49	1,295	643	1,938	204
50 ^b	109	51	160	198
51 ^b	273	33	306	186
52 ^b	385	34	419	186
53 ^b	670	37	707	186
54 ^b	845	30	875	186
56 ^b	273	29	302	186
57 ^b	285	30	315	
58 ^b	296	43		198
59 ^b	180	41	339	209
60 ^b	180		221	186
Total	34,489	34	214	186
Average per Pier	1,815	29,863	64,353	9,673
		1,572 ROACH STRUCTU	<i>3,387</i>	509
61	446	0	n⊑ 446	T
62	340	0	340	155
63	340	0 1	340	340 340
64	340	ō	340	340
65	341	0	341	341
66	0	0	0	0
67	0	0	0	Ö
68	0	0	0	0
69	0	0	0	0
70	0	0	0	0
71	340	0	340	0
72	340	0	340	0
73	340	0	340	0
74	340	0	340	0
75 76	577	0	577	577
77	526	0	526	526
78	464	0	464	464
Total	4,734	0	0	0
Average per Pier	263	0	4,734 263	3,083 171
	1 -00	<i>U</i> 1	ZD.3	171

^a Based on Richmond-San Rafael Bridge Maintenance Report dated March 1991.

^b Pier retrofit without pile cap

^c Bell piers.

Note: Pier 55 does not require retrofit - Piers 66-74 and 78 are land piers.